## 5,000 g, tension & compression

# FORCE GAUGE

Model: FG-5005 *ISO-9001, CE, IEC1010* 





### **FEATURES**

- \* 5,000 g, g/oz/Newton.
- \* Tension or Compression, Peak hold, Zero.
- \* Positive/ Reverse display.
- \* 5 digits LCD with back light.
- \* RS-232 computer interface.
- \* Full line accessories, optional test stand.
- \* DC 1.5V battery (UM-3, AA) x 6 or DC 9V adapter in.





The Art of Measurement

## 5,000 g x 1 g, g/oz/Newton, RS232

## **FORCE GAUGE**

Model: FG-5005

### **FEATURES**

*	Large LCD display with back light.
*	5,000 g, wide capacity, high resolution, high accuracy,
	high repeatability.
*	3 kind display unit : g, oz, Newton.
*	Tension & compression capability .
*	Peak hold (Max. load) can be held in display during
	make tension or compression measurement.
*	Zero button can operate both for normal measuring
	& the " peak hold " operation.
*	Full capacity zero (tare) control capability.
*	Fast/Slow response time push button.
*	Positive or reverse display direction select.
*	Full line accessories ( adapters ) are included.
*	Hand held & stand mounted gauges are available.
*	Low power consumption gives long battery life.
*	Build in low battery indicator.
*	Microprocessor circuit & exclusive load cell transducer.
*	Over load protection.
*	RS-232 computer interface.
*	Built-in DC 9V power adapter input socket.
*	Professional test stand (optional).

### **SPECIFICATIONS**

Display	LCD ( Liquid crystal display ).
	5 digits, 16 mm ( 0.63" ) digit size.
	Back light.
Display	Positive or Reverse direction, select by
Direction	the push button on the front panel.
Function	Tension & Compression (Push & Pull).
	Normal force, Peak hold (Max. load).
Peak hold	Will freeze the display value of the
	Peak load ( Max. load ).
Zero	Zero button can be operated both for
	"normal force" or "peak hold" operation
Unit select	g/oz/Newton
Measure	5,000 g/176.40 oz/49.03 Newton.
Capacity	
Resolution	1 g/0.05 oz/0.01 Newton.
Min. Display	3 g/0.10 oz/0.03 Newton.
Accuracy	$\pm$ ( 0.4 % + 1 digit ), within 23 $\pm$ 5 $^{\circ}$ C.
	* Under the test weight on 3000 g & 5000 g.

Update time	Fast Approx. 0.2 second.
	Slow Approx. 0.6 second.
Over range	Display show " " when in over
Indicator	range status.
Data output	RS-232 serial computer interface.
Overload	Max. 7 kg.
Capacity	
Full Scale	Approx. 2 mm max.
Deflection	
Zero/tare	Max. full capacity.
Control	
Circuit	Exclusive microprocessor LSI-circuit.
Power Supply	6 x 1.5 V AA (UM-3) size battery
	or DC 9V adapter (not included).
Power	Approx. DC 28 mA
Consumption	
Transducer	Exclusive load cell.
Operating	0°C to 50°C ( 32°F to 122°F ).
Temperature	
Operating	Less than 80% RH.
Humidity	
Dimension	215 x 90 x 45 mm ( 8.5 x 3.5 x 1.8 inch ).
Weight	650 g ( 1.43 LB )/with batteries.
Mounting	Main instrument with mounting holes are
Holes	provided on the back case, easy stand
	mounting.
Accessories	Operating manual1 PC.
Included	Flat-head adapter1 PC.
	Hook adapter1 PC.
	Cone head adapter1 PC.
	Chisel head adapter 1 PC.
	120 mm extension rod1 PC.
	Carrying case1 PC.
Optional	* Test stand, Model : FS-1001
Accessories	* Wedge grip, Model : WG-01
	* RS232 cable, Model : UPCB-01
	* USB cable, Model : USB-01
	* Software for data logging & data
	recorder.
	Model: SW-U801-WIN.

<sup>\*</sup> Appearance and specifications listed in this brochure are subject to change without notice.

# FORCE GAUGE

Model: FS-1001 *ISO-9001, CE, IEC1010* 



### **FEATURES**

- \* Optional; test stand, be connected with FG-5000A, FG-20KG, FG-5000A-232, FG-20KG-232, whole system will be a useful tool for material's tension and compression analysis.
- \* Size: 650 x 250 x 230 mm.





The Art of Measurement